

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Contaminated soil by wellhead needs to be removed.

Corrective Action: "Properly dispose of oily waste in accordance with 905.e

Date: 03/07/2024

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Bradenhead # 1

Comment: Plumbed to surface

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: gas motor

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 244762 Type: WELL API Number: 123-12557 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/09/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 2/29/24 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- UPRR 42 PAN AM AV1 Company Name- KPK API- 05-123-12557 In Weld County Colorado. While there, I observed SI well During this inspection the following possible compliance issues were observed: Contaminated soil. Rule 905.e. 3/7/24 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	02/29/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699505542	inspection pitures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6454365