

Big Run Production Company
Argenta Fee 18 & Argenta Fee 19
Location ID 333079
Inspection #700300642 Remediation

Corrective Action: Replace/install labels/placards per Rule 605

Action Taken: Removed tanks with placards

Corrective Action: Post proper emergency services number per Rule 605

Action Taken: Added emergency services numbers

Corrective Action: Remove all unused and non-servicable equipment or maintain and return to service

Action Taken: Removed chemical barrels and lube oil barrels. Pumpjack isn't ran continuously to minimize rod wear but will remain on location for intermittent artificial lift operations

Corrective Action: keep areas within 25' of equipment clear of weeds and combustible material

Action Taken: Removed weeds and combustible material

Corrective Action: Excavate or plumb bradenhead to allow for visual inspection per Rule 419.b

Action Taken: Made bradenheads accessible

Corrective Action: Conduct annual bradenhead test and submit via electronic Form 17 within 10 days of test and begin monthly monitoring per Rule 419

Action Taken: Conducted bradenhead tests on the Argenta 18 and Argenta 19 and began monthly monitoring

Corrective Action: Mark all rig anchors per Rule 1003

Action Taken: Located and Marked all rig anchors



Corrective Action: Mark all rig anchors per Rule 1003

Action Taken: Located and Marked all rig anchors



Corrective Action: ~400 bbl (not in use produced water tanks) are corroded, have holes and are nonservicable. Remove per Rule 606
Action Taken: Removed Tanks



Corrective Action: Clean up area around Argenta 18 well, remove unused equipment, self inspect for impacted material and remove. Repair wildlife screen at Argenta 19 well and install plug on top of chemical barrel. Per Rules 1002.f and 602.c

Action Taken: Removed barrels and cleaned up area around Argenta 18

