

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad
Location ID: 335347



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**
Section/Township/Range: 28 6S92W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad
Location ID: 335347



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad
Location ID: 335347



Photo # 9428 Tunnel erosion through berm/berm needs maintenance (N/NE area of location)



Photo # 9429 Tunnel erosion through berm/berm needs maintenance (N/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad
Location ID: 335347



Photo # 9430 Tunnel erosion through berm/erosion & transport of sediment off location (N/NE area on opposite side of berm just off location)

Photo # 9431 Tunnel erosion through berm/erosion & transport of sediment off location (N/NE area on opposite side of berm just off location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad
Location ID: 335347



Photo # 9432 Tunnel erosion through berm/berm needs maintenance (N/NE area of location)

Photo # 9433 Tunnel erosion through berm/berm needs maintenance (N/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad
Location ID: 335347



Photo # 9434 Tunnel erosion through berm/berm needs maintenance (N/NE area of location)



Photo # 9435 Failure to minimize erosion & transport of sediment off location/insufficient BMP's (E/SE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad
Location ID: 335347



Photo # 9436 Erosion & transport of sediment on slope (SE area of location)



Photo # 9437 Erosion & transport of sediment on slope (SE area of location)