

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad
Location ID: 335553



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost Site. Location is within Rule 411a Surface Water Intermediate Buffer & in close proximity to Rule 411b Generalized Intermediate & External Buffers. Location is approximately 230 yards from Mineota Ditch & 296 yards from Divide Creek.

Section/Township/Range: 13 6S92W

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad
Location ID: 335553



Location Overview:

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad
Location ID: 335553



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad
Location ID: 335553



Photo # 9779 Chemical containment approximately $\frac{3}{4}$ full of fluid/Failure to maintain chemical BMP/BMP insufficient to contain possible spill