

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403721620

Date Received:
03/15/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Lacey Granillo

5057870118

lgranillo@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 714000508

Inspection Date: 03/06/2024

FIR Submit Date: 03/07/2024

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 326593

Location Name: BONDAD 33-10-N33N10W Number: 11NWNE County: _____

Qtrqr: NWNE Sec: 11 Twp: 33N Range: 10W Meridian: N

Latitude: 37.121690 Longitude: -107.901720

FACILITY - API Number: 05-067-00 Facility ID: 326593

Facility Name: BONDAD 33-10-N33N10W Number: 11NWNE

Qtrqr: NWNE Sec: 11 Twp: 33N Range: 10W Meridian: N

Latitude: 37.121690 Longitude: -107.901720

CORRECTIVE ACTIONS:

2 CA# 192749

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: 03/14/2024

Response: CA COMPLETED

Date of Completion: 03/15/2024

Operator Comment: BMP have been installs and the rill erosion that was observed in the southeast and northeast portions of the disturbance is been repaired.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: BMP have been installs and the rill erosion that was observed in the southeast and northeast portions of the disturbance is been repaired.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lacey Granillo Signed: _____

Title: Regulatory Specialist Date: 3/15/2024 2:12:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403721620	FIR RESOLUTION SUBMITTED
403721647	714000508- completed
403721649	714000508- completed
403721650	714000508- completed
403721651	714000508- completed
403721652	714000508- completed

Total Attach: 6 Files