

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2024

Submitted Date:

03/20/2024

Document Number:

713600844

FIELD INSPECTION FORM

Loc ID 314215 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
4 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 83130
 Name of Operator: STRACHAN EXPLORATION INC
 Address: 992 S 4TH AVE SUITE 100-461
 City: BRIGHTON State: CO Zip: 80601

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Karen Voltura		karen.voltura@state.co.us	
ECMC Enforcement		dnr_cogccenforcement@state.co.us	
BEAR STACY L		stacy@strachanexploration.com	
Jordan LaPlante		jordan_laplante@fws.gov	
Harms, Jason		Jason@strachanexploration.com	
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275439	WELL	PR	06/01/2017	GW	099-06881	GRUENLOH 2	RI

General Comment:

This is a location inspection of the GRUENLOH #2 wellsite. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

	Type TANK LABELS/PLACARDS		
Comment:	There was no tank labels observed at the open top tank.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/20/2024

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1		Open Top		,	
Comment:	There was no wildlife protections or netting on the open top tank. There were 4 dead birds found floating in the tank covered with oily E&P waste. Operator was immediately notified on the day of inspection.					
Corrective Action:	Comply with 902.b. Install or repair wildlife protection equipment. Comply with 608.a.(13) for open top tanks.				Date:	03/15/2024

Paint

Condition	<input style="width: 90%; height: 20px;" type="text"/>	
Other (Content)	<input style="width: 95%; height: 20px;" type="text"/>	
Other (Capacity)	<input style="width: 95%; height: 20px;" type="text"/>	
Other (Type)	<input style="width: 95%; height: 20px;" type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	<input style="width: 90%; height: 20px;" type="text"/>				
Corrective Action:	<input style="width: 80%; height: 20px;" type="text"/>			Date:	<input style="width: 100px; height: 20px;" type="text"/>

Venting:

Yes/No	<input style="width: 95%; height: 20px;" type="text"/>		
Comment:	<input style="width: 95%; height: 20px;" type="text"/>		
Corrective Action:	<input style="width: 80%; height: 20px;" type="text"/>		Date: <input style="width: 100px; height: 20px;" type="text"/>

Flaring:

Type	<input style="width: 95%; height: 20px;" type="text"/>		
Comment:	<input style="width: 95%; height: 20px;" type="text"/>		

Corrective Action:

Date:

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)		
	Tanks	Inadequate	37.972960	-102.501200	
Comment	There was no wildlife protections or netting on the open top tank. There were 4 dead birds found floating in the tank covered with oily E&P waste. Operator was immediately notified on the day of inspection.				
Corrective Action	With the discovery of deceased migratory birds in the open topped tank that had no BMPs to protect the wildlife, Strachan is now required to remove the fluids from the tank to ensure that no endangered, threatened or additional migratory bird species have died in the E&P waste. ECMC Staff Ryan Costa must be notified via a Form 42 Notice of Other no less than 72 hours before the tank the fluid is removed so ECMC staff, and possibly other regulatory agencies, can observe the removal of the fluids to determine whether additional wildlife is present in the fluids and that proper disposal of the E&P waste is conducted.			Date:	03/29/2024

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600845	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6474450