

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2024

Submitted Date:

03/20/2024

Document Number:

713300724

FIELD INSPECTION FORMLoc ID 317651 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239692	WELL	SI	05/01/2021	GW	123-07480	SUCKLA-BROWN UNIT 1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric/automation panel, metal panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	electrical and automation panels		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239692 Type: WELL API Number: 123-07480 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/22/2024

BradenHead

Date of Last Brhd Test: 06/09/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p><u>ECMC Inspection Report Summary</u> <u>Inspector Michael Kester,</u> <u>conducted an on-site inspection.</u> <u>Location: Suckla Brown UT 1</u> <u>Operator: KPK</u> <u>API#: 123-07480</u> <u>County: Weld</u> <u>While there, I observed well site with pumping unit,</u> <u>During this inspection, the following possible compliance issues were observed:</u> <u>Mechanical integrity Testing, Rule 417b, corrective action date 4-22-2024</u></p> <p><u>Weather conditions: sunny and dry</u> <u>A follow up on this site inspection needs to be conducted to ensure the</u> <u>Compliance issues have been corrected to comply with ECMC rules.</u> <u>This is a summary of inspection report.</u></p> <p><u>This inspection does not nullify any orders or NOAV from the ECMC</u> <u>This is a continuing education inspection</u></p>	kestern	03/20/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
713300725	site pic	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6475700