

Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1722 From entrance to location



Photo # 1723 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1724 Location



Photo # 1725 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1726 Location



Photo # 1727 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1728 Location



Photo # 1729 Unmarked deadman

Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1730 PRV's do not comply with CECMC pressure safety device rules.



Photo # 1731 PRV's do not comply with CECMC pressure safety device rules.

Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1732 Unused equipment



Photo # 1733 Separator burner exhaust stack lacks bird protection/does not comply with CECMC wildlife rules.

Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1734 Dead weeds/debris



Photo # 1735 Dead weeds/debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1736 Debris



Photo # 1737 Debris



Inspection Photos

Location Name: TEP Rocky Mountain LLC KNIGHT GV 64-5 Pad

Location # 334652



Photo # 1738 Dead weeds/debris



Photo # 1739 Dead weeds/debris in secondary containment