

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403717453

Date Received:

04/03/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708901228

Inspection Date: 08/03/2023

FIR Submit Date: 08/05/2023

FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324285

Location Name: CLOUGH-66S94W Number: 13NWSW County:

Qtrqtr: NWS Sec: 13 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.521939 Longitude: -107.845779

FACILITY - API Number: 05-045-00 Facility ID: 324285

Facility Name: CLOUGH-66S94W Number: 13NWSW

Qtrqtr: NWS Sec: 13 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.521939 Longitude: -107.845779

CORRECTIVE ACTIONS:

1 CA# 177409

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 08/20/2023

Response: CA COMPLETED

Date of Completion: 11/06/2023

Operator Comment: Erosion occurring off the working has been repaired. Pad has been stabilized to prevent future run-off into vegetated areas. Corrective Action complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Erosion occurring off the working has been repaired. Pad has been stabilized to prevent future run-off into vegetated areas. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 4/3/2024 9:55:15 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files