

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403717453

Date Received:

04/03/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708901228

Inspection Date: 08/03/2023

FIR Submit Date: 08/05/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324285

Location Name: CLOUGH-66S94W Number: 13NWSW County: _____

Qtrqr: NWS Sec: 13 Twp: 6S Range: 94W Meridian: 6
W

Latitude: 39.521939 Longitude: -107.845779

FACILITY - API Number: 05-045-00 Facility ID: 324285

Facility Name: CLOUGH-66S94W Number: 13NWSW

Qtrqr: NWS Sec: 13 Twp: 6S Range: 94W Meridian: 6
W

Latitude: 39.521939 Longitude: -107.845779

CORRECTIVE ACTIONS:

1 ☒ CA# 177409

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 08/20/2023

Response: CA COMPLETED

Date of Completion: 11/06/2023

Operator Comment: Erosion occurring off the working has been repaired. Pad has been stabilized to prevent future run-off into vegetated areas. Corrective Action complete.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Erosion occurring off the working has been repaired. Pad has been stabilized to prevent future run-off into vegetated areas. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 4/3/2024 9:55:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403717453	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files