

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad
Location # 413055



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas & in close proximity
to NSO Habitat area. Location is within Rule 411a Surface
Water Internal Buffer.**

Section/Township/Range: 17 7S95W



Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad
Location # 413055



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad
Location # 413055



Photo # 1611 From inspection 708903397 conducted on 03/27/2024 Failure to maintain chemical BMP/chemical containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill.



Photo # 2920 Failure to maintain chemical BMP/chemical containment approximately 3/4 to 7/8 full of fluid/BMP insufficient to contain possible spill.