

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403744734

Date Received:

04/05/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

Heil, John

john.heil@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708903452

Inspection Date: 04/04/2024

FIR Submit Date: 04/04/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 413055

Location Name: WATSON RANCH PAD Number: 24B-17-07-95 County: \_\_\_\_\_

Qtrqtr: SESW Sec: 17 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.432958 Longitude: -108.025213

### FACILITY - API Number: 05-045-00 Facility ID: 413055

Facility Name: WATSON RANCH PAD Number: 24B-17-07-95

Qtrqtr: SESW Sec: 17 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.432958 Longitude: -108.025213

### CORRECTIVE ACTIONS:

1 ☒ CA# 194025

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 04/05/2024

Response: CA COMPLETED

Date of Completion: 04/04/2024

Operator Comment: At approximately 5:00 p.m. on 04/04/24, Wayne Smelser notified TEP of a leaking chemical container at the Watson A pad. Wayne stated that the containment was almost full but had not overtopped the secondary containment base yet. Wayne stated that this is an official 24-hour notification to get the leaking tank repaired /

replaced. Immediately after speaking with Wayne, TEP responded by to the location and recovered the contents of the defective tank and the containment. As of 12:00 p.m. on 04/05/24, Multi-chem had replaced the defective tank and checked integrity of the new tank and lines. This 24-hour corrective action has been completed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Defective tank has been removed and contents recovered. New chem tank installed on 04/05/24. Corrective action #194025 has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 4/5/2024 1:02:30 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403744734	FIR RESOLUTION SUBMITTED
403744851	New chem tank replaced on 04/05/24
403744852	Area around both chem tanks showing no release / staining on the ground

Total Attach: 3 Files