

OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands. File in triplicate for State lands.

RECEIVED

OCT 27 1969

COLO. OIL & GAS CONS. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [] GAS WELL [x] OTHER []
2. NAME OF OPERATOR Frank H. Walsh
3. ADDRESS OF OPERATOR Box 30, Sterling, Colorado 80751
4. LOCATION OF WELL NE SE NE Sec 17, T9N, R56W, (1650' FNL, 330' FEL)
5. LEASE DESIGNATION AND SERIAL NO.
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Chapel
9. WELL NO. #2
10. FIELD AND POOL, OR WILDCAT Cotton Valley
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 17-9N-56W
12. COUNTY OR PARISH Weld
13. STATE Colorado
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4501' GR



16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF [], PULL OR ALTER CASING [], FRACTURE TREAT [], MULTIPLE COMPLETE [], SHOOT OR ACIDIZE [], ABANDON [x], REPAIR WELL [], CHANGE PLANS [], (Other) []
SUBSEQUENT REPORT OF: WATER SHUT-OFF [], REPAIRING WELL [], FRACTURE TREATMENT [], ALTERING CASING [], SHOOTING OR ACIDIZING [], ABANDONMENT [], (Other) []

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work November 15, 1969.

Present Condition of Well

Total Depth 5882'
9 5/8" surface casing cemented at 155' with 110 sks.
5 1/2" production casing cemented at 5880' with 175 sks.
Perforations ("D" Sand) 5746-5750' and 5756-5757', 36 holes - squeezed with 100 sks. Perforations ("J" Sand) 5827-5835', 4 HPF. Open.
Status: Shut in because of water intrusion.

Proposed Work

- 1. Blow well down and fill with mud.
2. Plug No. 1 5850-5700', 20 sks.
3. Cut and recover 5 1/2" casing. Plug No. 2 across 5 1/2" stub with 20 sks.
4. Plug No. 3 180-100', 20 sks.
5. Plug No. 4 surface with 5 sks.
6. Cut off casing head and erect marker.
7. Clean and restore location.

Table with 2 columns and 5 rows: DVR, FJP, HHM, JAM, JJD. Checkmarks are present in the second column for FJP, HHM, JAM, and JJD.

18. I hereby certify that the foregoing is true and correct
SIGNED [Signature] TITLE Owner DATE October 24, 1969

(This space for Federal or State office use)
APPROVED BY [Signature] TITLE DIRECTOR DATE OCT 28 1969

