

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403746244

Date Received:

04/09/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708903415

Inspection Date: 03/28/2024

FIR Submit Date: 03/31/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 334652

Location Name: KNIGHT-67S95W Number: 5SENE County: \_\_\_\_\_

Qtrqtr: SENE Sec: 5 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.468502 Longitude: -108.015422

### FACILITY - API Number: 05-045- -00 Facility ID: 334652

Facility Name: KNIGHT-67S95W Number: 5SENE

Qtrqtr: SENE Sec: 5 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.468502 Longitude: -108.015422

### CORRECTIVE ACTIONS:

1 CA# 193772

Corrective Action: Comply with CECMC wildlife rules.

Date: 04/07/2024

Response: CA COMPLETED

Date of Completion: 04/06/2024

Operator Comment: Bird protection has been installed on the burner stacks and is now compliant with CECMC wildlife rules.  
Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC Representative:	
----------------------	--

2

CA# 193773

Corrective Action:	Comply with CECMC pressure safety device rules	Date: 04/07/2024
Response:	CA COMPLETED	Date of Completion: 04/02/2024
Operator Comment:	Proper pressure safety devices have been installed on each PRV. Corrective Action complete.	
ECMC Decision:		
ECMC Representative:		

3

CA# 193774

Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.	Date: 04/14/2024
Response:	CA COMPLETED	Date of Completion: 04/06/2024
Operator Comment:	Deadman anchor has been properly marked. Corrective Action complete.	
ECMC Decision:		
ECMC Representative:		

OPERATOR COMMENT AND SUBMITTAL

Comment:	CA#193772: Bird protection has been installed on the burner stacks and is now compliant with CECMC wildlife rules. Corrective Action complete. CA#193773: Proper pressure safety devices have been installed on each PRV. Corrective Action complete. CA#193774: Deadman anchor has been properly marked. Corrective Action complete.
----------	---

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name:	Jordan Veith	Signed:	
Title:	TEP Representative	Date:	4/9/2024 10:42:21 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files