

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2024

Submitted Date:

04/09/2024

Document Number:

713900517**FIELD INSPECTION FORM**Loc ID 444717 Inspector Name: Hansen, Logan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , | | inspections@civiresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|--------------------------------------|-------------|
| 444717 | LOCATION | AC | | | - | Anschutz Equus Farms 4-62-20_21 SWNW | RI |

General Comment:[This is an Interim Reclamation and Stormwater Inspection.](#)

| | | | | |
|--|---|--------|--|------------------|
| Location | | | | |
| Overall Good: <input type="checkbox"/> | | | | |
| Emergency Contact Number: | | | | |
| Comment: | | | | Date: _____ |
| Corrective Action: | | | | |
| Good Housekeeping: | | | | |
| Type | | | | |
| Comment: | Missing wildlife netting on secondary containment. | | | |
| Corrective Action: | Comply with Rule 608. | | | Date: 05/13/2024 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| | | | | |
| Comment: | Stained soil observed near unplugged hose that appeared to have soil moved over it. | | | |
| Corrective Action: | Remove stained soil per Rule 912.a. | | | Date: 05/09/2024 |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Venting: | | | | |
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|----------|-------------|---|---------|----|---------------|----|
| Facility ID: | 444717 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment _____

This location does not comply with Reclamation rules. Rule 1002.c. states all stockpiled soils shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Best management practices to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Topsoil stockpile has significant weed cover- Russian thistle- with no perennial vegetation that would compete with the weedy vegetation and generally work to decrease weed growth.

Corrective Action _____

Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date **05/13/2024**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment It appears the Operator has performed interim reclamation activities and stabilization however, interim areas are dominated by Russian thistle with no germination of desirable perennial vegetation.

In addition, the wells associated with the location have been abandoned and therefore the location production pad should be reduced to only areas needed for production and the remaining should be interim reclaimed.

Corrective Action Perform reclamation on areas not needed for production as well as current interim areas in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date 05/13/2024Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

At the time of this inspection, no erosion issues were observed at the location or along the access road.

Operator shall continue to monitor and manage this site for stormwater run on and runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 713900520 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6502138 |