

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403746244

Date Received:

04/09/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708903415

Inspection Date: 03/28/2024

FIR Submit Date: 03/31/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334652

Location Name: KNIGHT-67S95W Number: 5SENE County: _____

Qtrqtr: SENE Sec: 5 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.468502 Longitude: -108.015422

FACILITY - API Number: 05-045- -00 Facility ID: 334652

Facility Name: KNIGHT-67S95W Number: 5SENE

Qtrqtr: SENE Sec: 5 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.468502 Longitude: -108.015422

CORRECTIVE ACTIONS:

1 ☒ CA# 193772

Corrective Action: Comply with CECMC wildlife rules.

Date: 04/07/2024

Response: CA COMPLETED

Date of Completion: 04/06/2024

Operator Comment: Bird protection has been installed on the burner stacks and is now compliant with CECMC wildlife rules.
Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

2 ☒ CA# 193773

Corrective Action: Comply with CECMC pressure safety device rules

Date: 04/07/2024

Response: CA COMPLETED

Date of Completion: 04/02/2024

Operator
Comment: Proper pressure safety devices have been installed on each PRV. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

3 ☒ CA# 193774

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 04/14/2024

Response: CA COMPLETED

Date of Completion: 04/06/2024

Operator
Comment: Deadman anchor has been properly marked. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA#193772: Bird protection has been installed on the burner stacks and is now compliant with CECMC wildlife rules. Corrective Action complete.
CA#193773: Proper pressure safety devices have been installed on each PRV. Corrective Action complete.
CA#193774: Deadman anchor has been properly marked. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 4/9/2024 10:42:21 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403746244	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files