

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403757480

Date Received:  
04/18/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10261

Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Brad Rogers

303.229.1228

brogers@bayswater.us

All Inspections

wellinspections@bayswater.us

### ECMC INSPECTION SUMMARY:

FIR Document Number: 697505048

Inspection Date: 01/15/2024

FIR Submit Date: 01/25/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: BAYSWATER EXPLORATION & PRODUCTION LLC

Company Number: 10261

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 484898

Location Name: Onyx Number: Pad County: \_\_\_\_\_

Qtrqr: NWN Sec: 26 Twp: 7N Range: 66W Meridian: 6  
W

Latitude: 40.551861 Longitude: -104.753350

#### FACILITY - API Number: 05-123-00 Facility ID: 484898

Facility Name: Onyx Number: Pad

Qtrqr: NWN Sec: 26 Twp: 7N Range: 66W Meridian: 6  
W

Latitude: 40.551861 Longitude: -104.753350

### CORRECTIVE ACTIONS:

1 CA# 191352

Corrective Action:

Date: 02/22/2024

Operator shall provide the following:

- 1) Submit the test pit location information as the Exploration Plan of the Geotechnical analysis via Form 4 Sundry Notice to the attention of Chris Binschus.
- 2) Submit soil horizon thickness and evaluation data provided in a Geotechnical report via Form 4 Sundry Notice to the attention of Chris Binschus.
- 3) Provide the depth of the 8" crude oil gathering line (shown in Photo #3) and justification for not salvaging the plow layer. Note- the landowner was conducting agricultural practices after the 8" crude oil gathering line was installed, likely tilling to a depth of 12" (plow layer).

Response: CA COMPLETED

Date of Completion: 04/17/2024

Operator Comment: The attached topsoil thickness evaluation and evaluation data satisfies Item 2 above and contains the test pit location to satisfy Item 1. The depth of the existing flowline is 5' below ground cover - satisfying corrective action item 3.

ECMC Decision:

ECMC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Garrett

Signed:

Title: Sr. Regulatory Analyst

Date: 4/18/2024 1:42:34 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403757510	Topsoil Investigation
-----------	-----------------------

Total Attach: 1 Files