

Operator: *BONANZA CREEK ENERGY OPERATING*

Location Name: *State Pronghorn P-16 Pad*

Loc ID: *428090*

Inspection: *708201166*



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I



Exhibit J



Exhibit K



Exhibit L



Exhibit M



Exhibit N



Exhibit O

CA: Tank labels are peeling/faded/cracked and require replacement. Install sign to comply with Rule 605.g.

CA Resolution: Tank labels have been installed to comply with Rule 605.g.

CA: Trash/debris observed throughout the location. Comply with Rule 606 and remove all trash/debris from the location.

CA Resolution: Trash/debris has been removed to comply with Rule 606.

CA: Stained soil observed within secondary containment and at pumpjacks. Properly dispose of oily waste in accordance with Rule 905.e.

CA Resolution: Oily waste has been properly disposed of in accordance with Rule 905.e.

CA: This location does not comply with Rule 1003. During this inspection, it was observed that the interim areas are not progressing towards interim reclamation standards with evidence of un-stabilized/bare soils and undesirable vegetation (e.g. Russian thistle) throughout. Additional reclamation activities are required. Perform reclamation in accordance with Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil and continue to monitor and manage this site until the location meets Rule 1003 standards.

CA Resolution: Reclamation has been performed in accordance with Rule 1003.