

WELL NAME: HILL RANCH 16-1, API #: 071-08368, INSP. # 695109500



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT



PHOTO 4: LEAKS ON PUMP JACK PRIME MOVER HAS RESULTED IN IMPACTED SOIL JUST OFF PUMP JACK PAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D AND Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. (i>e REPAIR LEAKS) CA DATE 5-22-2024.



PHOTO 5: NOTE NFPA STICKERS ARE STILL LABELED WITH OLD OPERATOR WITH AN OLD PHONE NUMBER POSTED. Install sign to comply with Rule 605.h. (OLD OPERATOR EMERGENCY CONTACT NUMBERS SHALL NOT BE POST ON LOCATION.) CA DATE 5-22-2024.