

# Inspection Photos

04/19/2024

**Operator:** TEP ROCKY MOUNTAIN LLC - 96850

**Location ID:** 324039

**Inspection Doc:** 696205763

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324039



April 19, 2024



April 19, 2024

**Photo 1:** Photos 1-2 taken from the west end of the Location. Photo provides and overview from north, northeast, southeast to south. Photos also show signage missing from the battery facility.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324039



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324039



**Photo 3:** Lines at tanks missing cap/plug. Photo right shows line at condensate is leaking, with fluids spilling out of the honeypot. Inspector contacted/left message with Operator upon discovery. Leak requires stopping, and fluids/impacts require removal/cleaning.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324039




Photo 4: Wellhead. Sign is fading.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324039



**Photo 5:** Unused equipment (Fence, pipe) observed at the separator equipment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324039



**Photo 6:** Photos taken from the Location entrance. Runoff from the pad is resulting in erosion, degradation and sediment transport. Stormwater and erosion control BMPs missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources