

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2024

Submitted Date:

04/17/2024

Document Number:

713600939

## FIELD INSPECTION FORM

Loc ID 308564 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
308564	LOCATION	AC			-	ITTY BITTY-631S65W 31SWNW	RI

**General Comment:**

This is a follow up inspection at the ITTY BITTY #12-31 wellsite.  
See attached photos and additional details within this report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	The electric panel has been repaired.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		There is still stained soils by the engine skid and oil in the skid that needs to be cleaned up better. There is also signs of elk track by the engine skid and a fence panels should be considered to protect this area.				
Corrective Action:		Implement or modify BMPs for improved material handling and spill prevention. Clean up per Rule 1002.f.(2)B.				Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403757845	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511898">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511898</a>
713600940	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511895">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511895</a>