

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403761134

Date Received:

04/19/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Walter, Kyle

kwalter@enduringresources.com

Huntington, Heather

hhuntington@enduringresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000585

Inspection Date: 03/19/2024

FIR Submit Date: 03/25/2024

FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

LOCATION - Location ID: 326255

Location Name: HILL-N34N8W Number: 8SWNW County: _____

Qtrqtr: SWN Sec: 8 Twp: 34N Range: 8W Meridian: N
W

Latitude: 37.232343 Longitude: -107.776436

FACILITY - API Number: 05-067- -00 Facility ID: 326255

Facility Name: HILL-N34N8W Number: 8SWNW

Qtrqtr: SWN Sec: 8 Twp: 34N Range: 8W Meridian: N
W

Latitude: 37.232343 Longitude: -107.776436

CORRECTIVE ACTIONS:

1 ☒ CA# 193511

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 04/01/2024

Response: CA COMPLETED

Date of Completion: 04/04/2024

Operator Comment: PHOTOS OF CORRECTIVE ACTION ATTACHED

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

2 ☒ CA# 193512

Corrective Action: Comply with rule 606. Remove and properly store unused equipment.

Date: 04/09/2024

Response: CA COMPLETED

Date of Completion: 04/05/2024

Operator Comment: PHOTOS OF CORRECTIVE ACTION ATTACHED

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

3 ☒ CA# 193513

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 04/08/2024

Response: CA COMPLETED

Date of Completion: 04/15/2024

Operator Comment: PHOTOS OF CORRECTIVE ACTION ATTACHED

ECMC Decision: Approved via an AMI

ECMC Representative: Per photo included in attachment provided by operator guy line anchor has been marked.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed:

Title: Permitting Tech

Date: 4/19/2024 7:44:55 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403761134	FIR RESOLUTION SUBMITTED
403761147	CA PHOTOS

Total Attach: 2 Files