

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403767618

Date Received:

04/24/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10755

Name of Operator: MORNINGSTAR OPERATING LLC

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Amy Byars

817-334-8096

abyars@mspartners.com

Connie Blaylock

817-334-7882

cblaylock@mspartners.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000674

Inspection Date: 04/12/2024

FIR Submit Date: 04/16/2024

FIR Status: _____

Inspected Operator Information:

Company Name: MORNINGSTAR OPERATING LLC

Company Number: 10755

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 333343

Location Name: PETERSON 32-6-N32N6W Number: 14SESW County: _____

Qtrqtr: SESW Sec: 14 Twp: 32N Range: 6W Meridian: N

Latitude: 37.013660 Longitude: -107.470390

FACILITY - API Number: 05-007- -00 Facility ID: 333343

Facility Name: PETERSON 32-6-N32N6W Number: 14SESW

Qtrqtr: SESW Sec: 14 Twp: 32N Range: 6W Meridian: N

Latitude: 37.013660 Longitude: -107.470390

CORRECTIVE ACTIONS:

1 ☒ CA# 194296

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/23/2024

Operator
Comment: Debris removed 4/23

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.		
----------------------	--	--	--

2 ✔ CA# 194297

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Response: CA COMPLETED Date of Completion: 04/23/2024

Operator Comment: Equipment has been cleaned

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

Date: 04/22/2024

3 ✔ CA# 194298

Corrective Action: comply with rule 608a Install or repair wildlife protection equipment.

Response: CA COMPLETED Date of Completion: 04/23/2024

Operator Comment: Wildlife protection equipment has been repaired.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

Date: 04/22/2024

OPERATOR COMMENT AND SUBMITTAL

Comment: As of 4/23, debris has been removed, equipment cleaned up, and wildlife protection equipment repaired.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock Signed: _____

Title: Regulatory Analyst Date: 4/24/2024 11:07:18 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403767618	FIR RESOLUTION SUBMITTED
403767665	Photo 1 Debris Removed
403767668	Photo 2 Debris Removed
403767671	Photo 3 Debris Removed
403767676	Photo 14-2 Equipment cleaned
403767681	Photo 1, 14-4 Wildlife Protection Repaired
403767684	Photo 2, 14-4 Wildlife Protection Repaired

Total Attach: 7 Files