

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403770107

Date Received:

04/25/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10755

Name of Operator: MORNINGSTAR OPERATING LLC

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Amy Byars

abyars@mspartner.com

Connie Blaylock

cblaylock@mspartner.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000665

Inspection Date: 04/12/2024

FIR Submit Date: 04/16/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: MORNINGSTAR OPERATING LLC

Company Number: 10755

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

### LOCATION - Location ID: 333334

Location Name: CHAPIN 32-6-N32N6W Number: 23NWNE County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 23 Twp: 32N Range: 6W Meridian: N

Latitude: 37.006850 Longitude: -107.467030

### FACILITY - API Number: 05-007- -00 Facility ID: 333334

Facility Name: CHAPIN 32-6-N32N6W Number: 23NWNE

Qtrqtr: NWNE Sec: 23 Twp: 32N Range: 6W Meridian: N

Latitude: 37.006850 Longitude: -107.467030

### CORRECTIVE ACTIONS:

1 ☒ CA# 194292

Corrective Action: Comply with rule 606. Remove and properly store unused equipment.

Date: 05/01/2024

Response: CA COMPLETED

Date of Completion: 04/24/2024

Operator  
Comment:

Unused equipment has been removed.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.
----------------------	--

2  CA# 194293

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: 04/24/2024

Response: CA COMPLETED

Date of Completion: 04/24/2024

Operator Comment:	Thistle removed; soil stabilized.
-------------------	-----------------------------------

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.
----------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed:

Title: Regulatory Analyst

Date: 4/25/2024 3:11:03 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403770107	FIR RESOLUTION SUBMITTED
403770124	Photo 1
403770125	Photo 2
403770128	Photo 3
403770132	Photo 4
403770135	Photo 5
403770140	Photo 6

Total Attach: 7 Files