

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
401967245

Date Received:  
03/11/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tesla Dougherty</u>	<u>970-304-5245</u>	<u>tesla.dougherty@nblenergy.com</u>
<u>Abby Bazin</u>	<u>720-587-2356</u>	<u>abby.bazin@nblenergy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 674902584

Inspection Date: 02/26/2019

FIR Submit Date: 03/05/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 458932

Location Name: D23-14 Number: Pad County: \_\_\_\_\_

Qtrqtr: SESW Sec: 23 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.205850 Longitude: -104.520770

FACILITY - API Number: 05-123-00 Facility ID: 458932

Facility Name: D23-14 Number: Pad

Qtrqtr: SESW Sec: 23 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.205850 Longitude: -104.520770

CORRECTIVE ACTIONS:

**1** CA# 122901

Corrective Action: Install, repair, or replace required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 02/14/2019

Response: CA COMPLETED

Date of Completion: 02/14/2019

Operator Comment: The inspector's photos noted a gap in the Filtrexx that formed the basis for this corrective action. The gap in the Filtrexx was created to allow temporary access to the pad during active construction. Without the gap, vehicles and equipment would drive over the Filtrexx and destroy it. Noble closed the gap each evening at the conclusion of the day's activities. At this location, the main access has since been completed, so the temporary access and the gap are no longer needed and the Filtrexx has been permanently repaired, as shown in the attached photo.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 3/11/2019 9:23:46 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401967245	FIR RESOLUTION SUBMITTED
401967277	D23-14 Location Photo

Total Attach: 2 Files