

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401982184

Date Received:

03/27/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10687

Name of Operator: ELEVATION MIDSTREAM LLC

Address: 370 17TH ST SUITE 5300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jeff Rickard

jrickard@extractionog.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 674902607

Inspection Date: 02/20/2019

FIR Submit Date: 02/22/2019

FIR Status: _____

Inspected Operator Information:

Company Name: ELEVATION MIDSTREAM LLC

Company Number: 10687

Address: 370 17TH ST SUITE 5300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 460416

Location Name: BADGER CGF Number: _____ County: _____

Qtrqtr: NE4 Sec: 30 Twp: 1N Range: 67W Meridian: 6

Latitude: 40.027416 Longitude: -104.929729

FACILITY - API Number: 05-123- -00 Facility ID: 460416

Facility Name: BADGER CGF Number: _____

Qtrqtr: NE4 Sec: 30 Twp: 1N Range: 67W Meridian: 6

Latitude: 40.027416 Longitude: -104.929729

CORRECTIVE ACTIONS:

1 CA# 122688

Corrective Action: Submit topsoil management plan and explain why topsoil was mixed and how you calculated the amount of topsoil to be salvaged.

Date: 02/20/2019

Response: CA COMPLETED

Date of Completion: 03/22/2019

Operator Comment: Attached is the original Geotech report Elevation used to calculate out top soil. Elevation currently understands the expectation of the COGCC is to go beyond Geotech reports and have a certified ergonomist report prior to construction. As there's no reasonable way to separate the soil horizons that have been mixed, Elevation would like to work with COGCC Reclamation on a solution. Elevation currently proposes to contact a certified soil scientist contractor to draft a plan to amend the current stockpiles to transform them into useable topsoil for the future.

ECMC Decision: _____

ECMC
Representative:

2 CA# 122689

Corrective Action: Perform temporarily stabilization of the topsoil stockpiles. Per Rule 1002.c., all stockpiles shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Per Rule 1002.c., BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Date: 02/20/2019

Response: CA COMPLETED

Date of Completion: 02/22/2019

Operator
Comment:

Topsoil piles have been tracked and will be seeded. When favorable weather conditions/seasonal conditions conducive of seed germination and plant growth permit this spring.

ECMC Decision: _____

ECMC
Representative:

3 CA# 122690

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 02/08/2019

Response: CA COMPLETED

Date of Completion: 02/08/2019

Operator
Comment:

All operations were shut down the day of this inspection and waddles and silt fence were ordered and installed around the entire perimeter of the location.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Rickard

Signed: _____

Title: Regulatory Compliance Co

Date: 3/27/2019 3:05:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401982184	FIR RESOLUTION SUBMITTED
401982202	Topsoil Caculations PE Stamped

Total Attach: 2 Files