

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403648255

Date Received:

01/08/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 694100242

Inspection Date: 12/13/2023

FIR Submit Date: 12/22/2023

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 311389

Location Name: IKENOUYE-65N65W Number: 29NWSE County: _____

Qtrqtr: NWSE Sec: 29 Twp: 5N Range: 65W Meridian: 6

Latitude: 40.367400 Longitude: -104.682790

FACILITY - API Number: 05-123- -00 Facility ID: 311389

Facility Name: IKENOUYE-65N65W Number: 29NWSE

Qtrqtr: NWSE Sec: 29 Twp: 5N Range: 65W Meridian: 6

Latitude: 40.367400 Longitude: -104.682790

CORRECTIVE ACTIONS:

1 CA# 189510

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 01/05/2024

Response: CA COMPLETED

Date of Completion: 01/02/2024

Operator Comment: Spill pile BMP's corrected, berm has been fixed and the equipment is currently being used during the dig out of the impacts at the battery but has been piled up all together now. CA's complete.

ECMC Decision: _____

ECMC Representative:			
2	CA# 189511		
Corrective Action:	Comply with Rule 606		Date: <u>01/12/2024</u>
Response:	CA COMPLETED		Date of Completion: <u>01/02/2024</u>
Operator Comment:	Spill pile BMP's corrected, berm has been fixed and the equipment is currently being used during the dig out of the impacts at the battery but has been piled up all together now. CA's complete.		
ECMC Decision:			
ECMC Representative:			
3	CA# 189512		
Corrective Action:	Needs to be removed, or lined and contained with erosion control BMP. Install or repair required BMPs per Rule 1002.f.(2)C		Date: <u>01/05/2024</u>
Response:	CA COMPLETED		Date of Completion: <u>01/02/2024</u>
Operator Comment:	Spill pile BMP's corrected, berm has been fixed and the equipment is currently being used during the dig out of the impacts at the battery but has been piled up all together now. CA's complete.		
ECMC Decision:			
ECMC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	Spill pile BMP's corrected, berm has been fixed and the equipment is currently being used during the dig out of the impacts at the battery but has been piled up all together now. CA's complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Tyranny Bergin</u>	Signed: _____
Title: <u>H&S Specialist-Operations</u>	Date: <u>1/8/2024 4:24:25 PM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403648255	FIR RESOLUTION SUBMITTED
403648278	BMP
403648279	Berm
403648280	Equipment

Total Attach: 4 Files