

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403220274

Date Received:  
11/07/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1001 17TH STREET STE 1160  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
General		Inspections@catamountep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 700300443  
Inspection Date: 10/03/2022 FIR Submit Date: 10/05/2022 FIR Status:

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464  
Address: 1001 17TH STREET STE 1160  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 325488

Location Name: PINE RIVER UNIT-M34N6W Number: 31SWSE County: LA PLATA  
Qtrqtr: SWSE Sec: 31 Twp: 34N Range: 6W Meridian: M  
Latitude: 37.142565 Longitude: -107.538958

FACILITY - API Number: 05-067-00 Facility ID: 214877

Facility Name: Pine River Unit 3-31 Number: 1  
Qtrqtr: SWSE Sec: 31 Twp: 34N Range: 6W Meridian: M  
Latitude: 37.142565 Longitude: -107.538958

CORRECTIVE ACTIONS:

1 CA# 164993

Corrective Action: Continue clean up, file spill report. Repair liner and minimize and respond to releases during completion operations. Date: 10/07/2022

Response: CA COMPLETED Date of Completion: 10/05/2022

Operator Comment: Cleaned up location, repaired liner. Filed initial spill report Form #403189984 and subsequent #403198369.

ECMC Decision:

ECMC  
Representative:

**2** CA# 164995

Corrective Action: Repair/maintain installed BMPs and determine if additional BMPs are needed.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 11/03/2022

Operator  
Comment: Added BMPs to culverts and maintained ditches.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 165208

Corrective Action: Repair or replace liner if used for required spill prevention during completion operations.

Date: 10/07/2022

Response: CA COMPLETED

Date of Completion: 10/05/2022

Operator  
Comment: Repaired liner prior to completion operations.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: \_\_\_\_\_

Title: Geo/Eng Tech

Date: 11/7/2022 8:29:18 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403220274	FIR RESOLUTION SUBMITTED
403220414	Remediation Photos

Total Attach: 2 Files