

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403738527

Date Received:

04/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 41550

Name of Operator: TYLER ROCKIES EXPLORATION LTD

Address: P O BOX 119

City: TYLER State: TX Zip: 75710-0119

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Strawn, Mark

(930) 595-4886

texcomo@sbcglobal.net

ECMC INSPECTION SUMMARY:

FIR Document Number: 673709581

Inspection Date: 02/05/2015

FIR Submit Date: 02/23/2015

FIR Status: ACTION REQUIRED

Inspected Operator Information:

Company Name: TYLER ROCKIES EXPLORATION LTD

Company Number: 41550

Address: P O BOX 119

City: TYLER State: TX Zip: 75710-0119

LOCATION - Location ID: 320709

Location Name: AMOCO-UPRR-NOONEN-PRICE-64S59W Number: 11NWNW County: ARAPAHOE

Qtrqtr: NWN Sec: 11 Twp: 4S Range: 59W Meridian: 6

Latitude: 39.723877 Longitude: -103.962141

FACILITY - API Number: 05-005-00 Facility ID: 204603

Facility Name: AMOCO-UPRR-NOONEN-PRICE Number: 1

Qtrqtr: NWN Sec: 11 Twp: 4S Range: 59W Meridian: 6

Latitude: 39.723670 Longitude: -103.962030

CORRECTIVE ACTIONS:

1 CA# 4772

Corrective Action: Install sign to comply with rule 210.

Date: 03/27/2015

Response: CA COMPLETED

Date of Completion: 04/30/2015

Operator Comment: Inspection 4/30/2015 Document # 673710301 states "Corrective actions completed from the 2/5/2015, 673709581 inspection."

ECMC Decision: _____

ECMC
Representative:

2 CA# 15633

Corrective Action: Remove or remediate stained soil at pumpjack (see attached photo).

Date: 02/27/2015

Response: CA COMPLETED

Date of Completion: 04/30/2015

Operator
Comment: Inspection 4/30/2015 Document # 673710301 states "Corrective actions completed from the 2/5/2015, 673709581 inspection."

ECMC Decision: _____

ECMC
Representative:

3 CA# 21907

Corrective Action: Remove or remediate stained soil at wellhead (see attached photo).

Date: 02/27/2015

Response: CA COMPLETED

Date of Completion: 04/30/2015

Operator
Comment: Inspection 4/30/2015 Document # 673710301 states "Corrective actions completed from the 2/5/2015, 673709581 inspection."

ECMC Decision: _____

ECMC
Representative:

4 CA# 35430

Corrective Action: Install stormwater BMPs for erosion near propane tank and at the chemical container at wellhead.

Date: 03/27/2015

Response: CA COMPLETED

Date of Completion: 04/30/2015

Operator
Comment: Inspection 4/30/2015 Document # 673710301 states "Corrective actions completed from the 2/5/2015, 673709581 inspection."

ECMC Decision: _____

ECMC
Representative:

5 CA# 38472

Corrective Action: See Spill section for CA.

Date: 02/27/2015

Response: CA COMPLETED

Date of Completion: 04/30/2015

Operator
Comment: Inspection 4/30/2015 Document # 673710301 states "Corrective actions completed from the 2/5/2015, 673709581 inspection."

ECMC Decision: _____

ECMC
Representative:

6 CA# 43466

Corrective Action: Install sign to comply with rule 210.

Date: 03/27/2015

Response: CA COMPLETED

Date of Completion: 04/30/2015

Operator
Comment: Inspection 4/30/2015 Document # 673710301 states "Corrective actions completed from the 2/5/2015, 673709581 inspection."

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Donahue

Signed:

Title: Compliance Specialist

Date: 4/1/2024 4:15:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403738527	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files