

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401999343

Date Received:

04/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Tyranny Bergin

Phone

970-313-5547

Email

EHSCOGCCInspections@pdce.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 674902641

Inspection Date: 03/01/2019

FIR Submit Date: 03/14/2019

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 305082

Location Name: STONEBRAKER-62N64W Number: 28SWNE County: _____

Qtrqtr: SWNE Sec: 28 Twp: 2N Range: 64W Meridian: 6

Latitude: 40.111109 Longitude: -104.554562

FACILITY - API Number: 05-123- -00 Facility ID: 305082

Facility Name: STONEBRAKER-62N64W Number: 28SWNE

Qtrqtr: SWNE Sec: 28 Twp: 2N Range: 64W Meridian: 6

Latitude: 40.111109 Longitude: -104.554562

CORRECTIVE ACTIONS:

1 CA# 123224

Corrective Action: Perform reclamation in accordance to COGCC 1004 reclamation rules and requirements. Re-contour and re-grade access road and perform compact alleviation. Operator is directed to perform corrective actions outlined on this inspection report immediately. Doing so may decrease the duration of the alleged violations and the penalties that may be assessed pursuant to Rule 523.

Date: 05/25/2017

Response: CA COMPLETED

Date of Completion: 04/08/2019

Operator
Comment:

CA has been addressed amd reclamation work has been completed.

ECMC Decision: _____

ECMC
Representative:

2 CA# 123225

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 03/01/2019

Response: CA COMPLETED

Date of Completion: 04/08/2019

Operator
Comment:

CA has been addressed and erosion controls have been completed.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA's have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: _____

Title: EHS Coordinator

Date: 4/8/2019 11:02:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401999343	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files