

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2024

Submitted Date:

05/10/2024

Document Number:

707800944

**FIELD INSPECTION FORM**Loc ID 448834 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Fulcrum		inspections@fulcrumeo.com	
Penner, annalee		annalee@fulcrumef.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448969	WELL	PR	10/01/2023	OW	057-06593	Grizzly 0881 2-1H36	PR
448970	WELL	PR	11/01/2021	OW	057-06594	Grizzly 0881 4-1H36	PR
448974	WELL	SI	09/01/2023	OW	057-06597	Peters 0781 16-12H13	SI

**General Comment:****ECMC Inspection Report Summary**

On Wednesday 5/1/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Hebron 12 pad, at Location # 448834 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Well signage is missing on one well
2. Well signage lacks information (API)
3. Lack of battery signage
4. Random debris
5. Belt guard is off and laying on the ground

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	06/28/2024
Type	WELLHEAD		
Comment:	1. Well signage is missing on one well 2. Well signage lacks information (API)		
Corrective Action:	Provide proper signage	Date:	06/28/2024
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/970-594-0477

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Belt guard is off and laying on the ground		
Corrective Action:	Install all safety equipment	Date:	05/27/2024
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	05/27/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Other	# 1		
Comment:	Well head		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	Chemical tank in plastic containment	
Corrective Action:		Date:
Type: Emission Control Device	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Comment:		Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water.				
Corrective Action:						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403787122	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6543934">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6543934</a>
707800948	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6543927">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6543927</a>