

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403795110

Date Received:
05/17/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900513

Inspection Date: 04/04/2024

FIR Submit Date: 04/09/2024

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 429893

Location Name: Latham 14-12 Number: Facility County: _____

Qtrqtr: SESE Sec: 11 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.320820 Longitude: -104.397570

FACILITY - API Number: 05-123-00 Facility ID: 429893

Facility Name: Latham 14-12 Number: Facility

Qtrqtr: SESE Sec: 11 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.320820 Longitude: -104.397570

CORRECTIVE ACTIONS:

2 CA# 194145

Corrective Action: Remove fencing to comply with Rule 1004.

Date: 05/09/2024

Response: CA COMPLETED

Date of Completion: 04/23/2024

Operator
Comment:

Operator has reported that the fence was been removed from the east and north side of the facility location and the north side of the flowline corridor. The fence along the west side of the facility pad was left in place since it ties into the landowner's fence that continues to the north beyond location disturbance area. The fence along the location access road was left in place to prevent wildlife or future grazing of animals from accessing lease roads and pads. Operator also notes that they added a section with a drop gate along the south edge of where the facility was for access. Location currently complies with Rule 1004.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 5/17/2024 11:48:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403795210	Inspection Resolution Report
-----------	------------------------------

Total Attach: 1 Files