

Interim Reclamation and Stormwater Inspection

April 15, 2024

Operator: FULCRUM ENERGY OPERATING LLC- #10805

Location ID: 467526

Inspection Document #: 697505283

Jackson County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Spicer S32 Annex Pad
Location ID: 467526



Photo 1. Photo taken from the entrance of location. Photo illustrates the Location Operator sign for the western location. Staff did not observe a Location sign for the Spicer Annex Pad.



Photo 2. Photo taken from the southern location, facing West. Photo illustrates equipment along the western location.

Inspection Photos
Location Name: Spicer S32 Annex Pad
Location ID: 467526



Photo 3. Photo taken from the southern location, facing North. Photo illustrates equipment along the central location.



Photo 4. Photo taken from the southern location, facing Northeast. Photo illustrates the Operator has failed to perform interim reclamation and reduce the size of the location.

Inspection Photos
Location Name: Spicer S32 Annex Pad
Location ID: 467526



Photo 5. Photo taken from the eastern location, facing South. See comments under Photo 4. Note- there appears to be weed growth along the fill slope that will need to be managed in the future.



Photo 6. Photo taken from the eastern location, facing North. See comments under Photos 4 and 5.

Inspection Photos
Location Name: Spicer S32 Annex Pad
Location ID: 467526



Photo 7. Photo taken from the northeastern location, facing West. Photo illustrates the topsoil stockpile which will need to be managed after interim reclamation is performed.

Inspection Photos
Location Name: Spicer S32 Annex Pad
Location ID: 467526



Photo 8. ECMC GIS aerial imagery illustrates the location falls within Greater Sage Grouse Priority Habitat Management Area.