

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 24-4 Pit

Location # 334777

Facility ID: 414573



Photo # 6744 From entrance to location



Photo # 6745 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 24-4 Pit

Location # 334777

Facility ID: 414573



Photo # 6746 Location



Photo # 6747 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 24-4 Pit

Location # 334777

Facility ID: 414573



Photo # 6748 Location




Photo # 6749 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 24-4 Pit

Location # 334777

Facility ID: 414573



May 13, 2024 at 1:50:10 PM
CO

Photo # 6750 Open ended lines on out of service tank/wildlife hazards



May 13, 2024 at 1:49:22 PM
CO

Photo # 6751 Open ended lines on out of service tank/wildlife hazards

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 24-4 Pit

Location # 334777

Facility ID: 414573



Photo # 6752 Open ended lines on out of service tank/wildlife hazards



Photo # 6753 Open ended piping & port on out of service tank/wildlife hazards

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 24-4 Pit

Location # 334777

Facility ID: 414573



Photo # 6754 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 6755 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 24-4 Pit

Location # 334777

Facility ID: 414573



Photo # 6756 Debris



Photo # 6757 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 24-4 Pit

Location # 334777

Facility ID: 414573



Photo # 6758 Debris



Photo # 6759 Tank battery lacks signage