

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2024

Submitted Date:

05/20/2024

Document Number:

713900619

FIELD INSPECTION FORM

Loc ID 416717	Inspector Name: Hansen, Logan	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: ECMC Operator Number: 47120 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Address: P O BOX 173779 City: DENVER State: CO Zip: 80217-				Findings: 6 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416717	LOCATION	AC			-	SCHLAGEL 10-5HZ PAD	RI
479114	WELL	PR	09/01/2023	OW	123-51482	SCHLAGEL 5-3HZ	RI
479115	WELL	PR	09/01/2023	OW	123-51483	SCHLAGEL 5-2HZ	RI
479116	WELL	PR	08/01/2023	OW	123-51484	SCHLAGEL 5-9HZ	RI
479117	WELL	PR	08/01/2023	OW	123-51485	SCHLAGEL 5-8HZ	RI
479118	WELL	PR	08/01/2023	OW	123-51486	SCHLAGEL 5-7HZ	RI
479119	WELL	PR	07/01/2023	OW	123-51487	SCHLAGEL 5-11HZ	RI
479120	WELL	PR	08/01/2023	OW	123-51488	SCHLAGEL 5-5HZ	RI
479121	WELL	PR	08/01/2023	OW	123-51489	SCHLAGEL 5-10HZ	RI
479122	WELL	PR	07/01/2023	OW	123-51490	SCHLAGEL 5-4HZ	RI
479123	WELL	PR	07/01/2023	OW	123-51491	SCHLAGEL 5-1HZ	RI
479124	WELL	PR	07/01/2023	OW	123-51492	SCHLAGEL 5-6HZ	RI

General Comment: This is an Interim Reclamation and Stormwater Inspection.
--

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type				
Comment:	Stained soil observed around the wellheads.			
Corrective Action:	Remove stained soil per Rule 912.a.			Date: 06/20/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities

Facility ID: 416717	Type: LOCATION	API Number: -	Status: AC	Insp. Status: RI
---------------------	----------------	---------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479114	Type: WELL	API Number: 123-51482	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479115	Type: WELL	API Number: 123-51483	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479116	Type: WELL	API Number: 123-51484	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479117	Type: WELL	API Number: 123-51485	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479118	Type: WELL	API Number: 123-51486	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479119	Type: WELL	API Number: 123-51487	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479120	Type: WELL	API Number: 123-51488	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479121	Type: WELL	API Number: 123-51489	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479122	Type: WELL	API Number: 123-51490	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479123	Type: WELL	API Number: 123-51491	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479124	Type: WELL	API Number: 123-51492	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED, OTHER

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ In Process _____

Comment _____

Based on the staged equipment on the wellhead location pad it appears the topsoil stockpile is in the process of being stabilized. Confirmation of the success of protection of soils on the location will be determined during a future inspection date.

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ In _____

Comment _____

Tractors and other equipment was being stored on the wellhead pad, however it appeared the equipment was being staged for interim stabilization. Confirmation will be made during a future inspection date.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? Pass Production areas stabilized ? In
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established In

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Interim disturbance areas were in the process of being cross ripped as well as other interim reclamation procedures and will be inspected at a later date to confirm compliance.

Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

Corrective Action

Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:			
Corrective Action:			Date
Overall Final Reclamation	Well Release on Active Location	Multi-Well Location	

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:	Rill erosion was observed on the East side of the temporary tanks as well as along the base of the topsoil stockpile and the production pad.		
Corrective Action:	Repair erosion and install BMP's to stabilize the well location per Rule 1002.f.		Date: 05/27/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713900620	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555058