

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
05/08/2024  
Submitted Date:  
05/08/2024  
Document Number:  
699505777

**FIELD INSPECTION FORM**

Loc ID 318344 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**  
6 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241143	WELL	SI	04/01/2021	OW	123-08931	YOXALL FARMS 5	SI

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: wellhead sign is missing on well.

Corrective Action: Install sign to comply with Rule 605.d.

Date: 06/08/2024

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 241143 Type: WELL API Number: 123-08931 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_  
 Comment:   
 Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/27/2023 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment:   
 Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On 5/8/24 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Yoxall Farms5                      Company Name- KPK                      API- 05-123-08931                      In Weld County Colorado.                      While there, I observed SI well                      During this inspection the following possible compliance issues were observed:                      Wellhead sign missing. Rule 605 d. 6/8/24                      A follow up on this site inspection needs to be conducted to ensure the compliance issues                      have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p>	medinaj	05/08/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403790701	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6547890">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6547890</a>
699505778	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6547860">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6547860</a>