

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2024

Submitted Date:

05/17/2024

Document Number:

713601035

FIELD INSPECTION FORM

Loc ID 324837 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num:

Operator Information:

ECMC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213033	WELL	SI	01/01/2024	OW	061-06394	STAVELY 1-26	RI

General Comment:

This is a follow up of the previous reclamation inspections (#713600138,#713600434,#713600785).
Operator is directed to perform all outstanding corrective actions immediately.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type STORAGE OF SUPL

Comment: There are parts near the pumpjack that need to be removed.

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type Area Volume

Lube Oil Pump Jack

Comment: There is oily fluid that has overtopped the containment and spilled out by the pumpjack. Stained soils must be cleaned up. Previous corrective action has not been completed.

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Immediate clean up. Implement or modify BMPs for improved material handling and spill prevention.

Date:

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: The fence around the pump jack is inadequate to prevent livestock entry and is not maintained. There is an opening at the tank battery fence and the 2 wires will not keep livestock out. Previous corrective action has not been completed.

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403794657	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551665
713601036	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551661