

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2024

Submitted Date:

05/29/2024

Document Number:

707901539**FIELD INSPECTION FORM**Loc ID 336096 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
Medina, Justin		justin.medina@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240401	WELL	PR	10/30/1975	GW	123-08189	STATE 9	PR

**General Comment:**[Follow up inspection per doc # 699505642](#)

Location			
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:		Date: _____	
Good Housekeeping:			
Type	OTHER		
Comment:	Contaminated soil by wellhead needs to be removed		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e		Date: 04/06/2024
Type	OTHER		
Comment:	wellhead sign is covered by electric equipment and cannot read. Sign needs to be placed in a visible area		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 04/06/2024
Type			
Comment:	mechanical issue on wellhead, small leak was observed during inspection		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e		Date: 04/06/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 240401 Type: WELL API Number: 123-08189 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 08/22/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment

User

Date

ECMC Inspection Report Summary

On 5/29/24 I, Inspector Randy Silver conducted an on-site re-inspection Per

Doc#699505642 at:

Well Name- State 9

Company Name- KPK

API- 05-123-08189

In Weld County Colorado.

While there, I observed PR well

During this inspection the following possible compliance issues were observed:

Mechanical issue. Rule 608.e. 4/6/24

Contaminated soil. Rule 908.e. 4/6/24

Wellhead sign not visible. Rule 605.e. 4/6/24

At time of inspection it does not appear any corrective action have been address. This is the second inspection with not copliance.

This is a summary of inspection report.

silverr

05/29/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707901540	loc pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565991">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565991</a>