

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403801817

Date Received:

05/23/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Laramie

cogccnotifications@laramie-energy.com

Toews, Wesley

wtoews@blm.gov

ECMC INSPECTION SUMMARY:

FIR Document Number: 696205724

Inspection Date: 04/04/2024

FIR Submit Date: 04/10/2024

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 312476

Location Name: HORSESHOE CANYON-69S97W Number: 28SWSE County: _____

Qtrqr: SWSE Sec: 28 Twp: 9S Range: 97W Meridian: 6

Latitude: 39.239422 Longitude: -108.219874

FACILITY - API Number: 05-077-00 Facility ID: 312476

Facility Name: HORSESHOE CANYON-69S97W Number: 28SWSE

Qtrqr: SWSE Sec: 28 Twp: 9S Range: 97W Meridian: 6

Latitude: 39.239422 Longitude: -108.219874

CORRECTIVE ACTIONS:

1 ☒ CA# 194187

Corrective Action:

Comply with Rules 1004 and 1002.f: Conduct additional reclamation work within areas of the access road not progressing towards 1004 standards. Install or repair required stormwater and erosion control BMPs to manage runoff in a manner that minimizes erosion, degradation and sediment transport until long-term stabilization is achieved. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Date: 05/31/2024

Response: CA COMPLETED

Date of Completion: 05/22/2024

Operator Comment: Hand seeded areas of reclaimed road . Rake reeling and erosion

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed:

Title: Regulatory Specialist

Date: 5/23/2024 11:54:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403801817	FIR RESOLUTION SUBMITTED
403801819	CA Photos

Total Attach: 2 Files