

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403789554

Date Received:

05/14/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

COGCC.inspections@caerusoilandgas.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 696205784

Inspection Date: 04/29/2024

FIR Submit Date: 05/01/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 334558

Location Name: ROLES-67S93W Number: 13NESE County: \_\_\_\_\_

Qtrqtr: NWSE Sec: 13 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.444210 Longitude: -107.721290

### FACILITY - API Number: 05-045- -00 Facility ID: 334558

Facility Name: ROLES-67S93W Number: 13NESE

Qtrqtr: NWSE Sec: 13 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.444210 Longitude: -107.721290

### CORRECTIVE ACTIONS:

1 ☒ CA# 194818

Corrective Action: Comply with 603.o. Install or repair secondary containment measures at the tank battery facility.

Date: 06/01/2024

Response: CA COMPLETED

Date of Completion: 05/08/2024

Operator Comment: Liner was repaired, see photo.

ECMC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

ECMC Representative:	acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	---

2  CA# 194819

Corrective Action:	Comply with 1003.a. If anchors are no longer necessary on the Location, anchor should be removed pursuant to 606 requirements.
--------------------	--

Date: 06/01/2024

Response: CA COMPLETED

Date of Completion: 05/08/2024

Operator Comment:	Removed.
-------------------	----------

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 5/14/2024 10:26:21 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403789554	FIR RESOLUTION SUBMITTED
403789572	Liner was repaired

Total Attach: 2 Files