

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2024

Submitted Date:

05/23/2024

Document Number:

713900627**FIELD INSPECTION FORM**Loc ID 320644 Inspector Name: Hansen, Logan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		ed@renegadeoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204243	WELL	PR	01/01/2024	OW	005-06327	LOWRY STATE 13-25	RI
320644	LOCATION	AC			-	LOWRY STATE-65S65W 25SWSW	RI
470461	Location	AC			-	LOWRY STATE-65S65W 25SWSW	RI

General Comment:

This is an Interim Reclamation and Stormwater Inspection.

Note - ECMC Staff, Logan Hansen, contacted an Operator representative on 5/16/24 to discuss the observations from the inspection.

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Signs on the tank batteries are no longer legible.			
Corrective Action:	Install sign to comply with Rule 605.g.			Date: 06/23/2024
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Good Housekeeping:				
Type				
Comment:	Stained soil was observed around production equipment and on the production pad at the wellhead location.			
Corrective Action:	Remove stained soil per Rule 912.a.			Date: 06/23/2024
Type				
Comment:	Open top pipes across the well and tank battery location missing wildlife cover or cap. See inspection photos for details.			
Corrective Action:	Install wildlife protection equipment per Rule 608.a.			Date: 05/30/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: <input type="text"/>
Flaring:				
Type				
Comment:				
Corrective Action:				Date: <input type="text"/>

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment This location does not comply with Rule 1003.b. Due to erosion off the tank battery and well locations sediment has been carried off location and caused bare soil degradation off location. Interim reclamation should occur on all disturbance areas as a result of the erosion off location to minimize disturbance.

Corrective Action Perform reclamation in accordance with Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date **11/01/2024**

Overall Interim Reclamation **Fail**

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER

Comment:

Corrective Action:

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Stormwater sediment laden waters are leaving site on to adjacent lands approximately 550 feet off the tank battery pad and off of the well location. BMPs are in need of repair or replacement to comply with rule 1002.f.

Corrective Action:

Comply with rule 1002.f. Stormwater Management

Date:

06/23/2024

Pits:

NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403802315	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6560208
713900630	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6560195

Date Run: 5/30/2024 Doc [#713900627]

Page 6 of 6