



Form Resolution To Document Number: 709100264

Razor 10E Pad Photo Documentation

FIRR Doc#: 403773768

Drafted By:



Melissa Parrish

Cell: (720)795-3257

Email: mparrish@fundareresources.com

Production/ Compliance/ Regulatory/ Health & Safety



Razor 10E –

Wellhead Signage Has Been Replaced – In Accordance With Rule 605.d.



May 31, 2024 07:55:48
Colorado 14
Raymer
Weld County
Colorado

Razor 10E –

Debris Throughout Location Has Been Cleaned Up & Removed In
Accordance With Rule 606



May 31, 2024 07:55:59
Colorado 14
Raymer
Weld County
Colorado

Razor 10E –

Debris Throughout Location Has Been Cleaned Up & Removed In
Accordance With Rule 606



Razor 10E –

Debris & Unused Equipment Throughout Location Has Been Cleaned Up
& Removed In Accordance With Rule 606



Razor 10E –

Tank Battery Signage

Please Note – Air Tanks Are Required To Stay On Site For H2S (Sour Gas) Facility



May 31, 2024 07:59:30
County Road 127
Raymer
Weld County
Colorado

Razor 10E –

In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up
Impacted Gravel Within Tank Berm & Had Liner Inspection Performed
Due To Rule 912.b. Reportable Release Of Unknown Amount

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050



Razor 10E –

In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up
Impacted Gravel Within Tank Berm & Had Liner Inspection Performed Due
To Rule 912.b. Reportable Release Of Unknown Amount

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050



Razor 10E –

In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up Impacted Gravel Within Tank Berm & Had Liner Inspection Performed Due To Rule 912.b. Reportable Release Of Unknown Amount

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050



Razor 10E –

In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up Impacted Gravel Within Tank Berm & Had Liner Inspection Performed Due To Rule 912.b. Reportable Release Of Unknown Amount

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050



Razor 10E –

In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up Impacted Gravel Within Tank Berm & Had Liner Inspection Performed Due To Rule 912.b. Reportable Release Of Unknown Amount

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050



May 31, 2024 08:01:28
County Road 127
Raymer
Weld County
Colorado

Razor 10E –

**In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up Impacted Gravel
Within Tank Berm & Had Liner Inspection Performed Due To Rule 912.b. Reportable
Release Of Unknown Amount**

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050



Razor 10E –

In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up Impacted Gravel Within Tank Berm & Had Liner Inspection Performed Due To Rule 912.b. Reportable Release Of Unknown Amount

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050



Razor 10E –

In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up Impacted Gravel
Within Tank Berm & Had Liner Inspection Performed Due To Rule 912.b. Reportable
Release Of Unknown Amount

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050



May 31, 2024 08:10:21
County Road 127
Raymer
Weld County
Colorado

Razor 10E –

In Accordance With Rule 913.d. – Fundare Investigated, Cleaned Up Impacted
Gravel Within Tank Berm & Had Liner Inspection Performed Due To Rule 912.b.
Reportable Release Of Unknown Amount

Form 19 IS Doc# 403761730

Form 19 S Doc # 403771050




Razor 10E –

Stained Soil Beneath Heater Treater Was Properly Cleaned Up & Disposed Of In Accordance
With Rule 912.a.



Razor 10E –

Debris Throughout Location Has Been Cleaned Up & Removed In Accordance With Rule 606



Razor 10E –

Debris Throughout Location Has Been Cleaned Up & Removed In Accordance With Rule 606



Razor 10E –

Debris Throughout Location Has Been Cleaned Up & Removed In Accordance With Rule 606



Razor 10E –

Debris Throughout Location Has Been Cleaned Up & Removed In Accordance With Rule 606



Razor 10E –

Debris Throughout Location Has Been Cleaned Up & Removed In Accordance With Rule 606



Razor 10E –

Debris Throughout Location Has Been Cleaned Up & Removed In Accordance With Rule 606



Razor 10E –

Tumble Weeds That Were Located Within Fence Line Of Flare/Combustor Have Been Removed In Accordance With Rule 606



Razor 10E –

Tumble Weeds That Were Located Within Fence Line Of Flare/Combustor Have
Been Removed In Accordance With Rule 606