

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403809642

Date Received:

06/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Luke Kelly

Phone

970-939-6353

Email

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900517

Inspection Date: 04/04/2024

FIR Submit Date: 04/09/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 444717

Location Name: Anschutz Equus Farms Number: 4-62-20_21 SWNW County: _____

Qtrqtr: SWN Sec: 20 Twp: 4N Range: 62W Meridian: 6
W

Latitude: 40.299603 Longitude: -104.356372

FACILITY - API Number: 05-123- -00 Facility ID: 444717

Facility Name: Anschutz Equus Farms Number: 4-62-20_21 SWNW

Qtrqtr: SWN Sec: 20 Twp: 4N Range: 62W Meridian: 6
W

Latitude: 40.299603 Longitude: -104.356372

CORRECTIVE ACTIONS:

3 CA# 194150

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseedling is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date: 05/13/2024

Response: CA COMPLETED

Date of Completion: 05/29/2024

Operator Comment:	Operator has provided photo documentation to show that the location has been appropriately mowed to address any weeds and undesirable vegetation. The area has been seeded, and straw crimped to provide stabilization and promote more uniform future growth. Location currently complies with Rule 1002.c.	
ECMC Decision:	<hr/>	
ECMC Representative:	<div></div>	

4 CA# 194151

Corrective Action:	Perform reclamation on areas not needed for production as well as current interim areas in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.	Date: 05/13/2024
Response:	CA COMPLETED	Date of Completion: 05/29/2024
Operator Comment:	Operator has provided photo documentation to show that the location has been appropriately mowed to address any weeds and undesirable vegetation. The area has been seeded, and straw crimped to provide stabilization and promote more uniform future growth.. Location currently complies with Rule 1003.	
ECMC Decision:	<hr/>	
ECMC Representative:	<div></div>	

OPERATOR COMMENT AND SUBMITTAL

Comment:	CA follow-up has been completed for this location.
----------	--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan Signed: _____

Title: Sr Regulatory Analyst Date: 6/4/2024 5:41:45 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403812464	Inspection Report Resolution

Total Attach: 1 Files