

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2024

Submitted Date:

06/04/2024

Document Number:

709100310

FIELD INSPECTION FORMLoc ID 312317 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 17180

Name of Operator: CITATION OIL & GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rogers, Bob		brogers@cogc.com	
Harris, Debra		dharris@cogc.com	
Kennedy, Herschel		hkennedy@cogc.com	
WARD, SHARON		sward@cogc.com	
Kym Shure		kym.schure@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265071	WELL	PR	02/01/2023	OW	075-09333	FLUHARTY 1	EI

General Comment:

On May 23, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the FLUHARTY-69N52W/6NWNE location (Location ID: 312317).

The location is in close proximity to Beall Creek.

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Tumbleweeds present in fence.		
Corrective Action:	Comply with Rule 606		Date: 09/04/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (wooden posts) on location.		
Corrective Action:	Comply with Rule 606		Date: 09/04/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
Lube Oil	WELLHEAD			
Comment:	At the time of this inspection, Staff observed a hydrocarbon release/spill at the polish rod and on nearby soil. Staff was unable to determine the approximate volume. See photo documentation.			
Corrective Action:	Immediately remove oily waste. Removal of impacted soils in excess of Table 915-1 or other remedial activities must be initiated to fully define the vertical and horizontal extent of impacts at the remediation site. Rule 912.a(5) requires that any spills or releases that do not meet the reporting requirements of Rule 912.b, Operators will document and cleanup efforts and provide documentation of the cleanup to the director upon request. Perform cleanup of this area and provide documentation of the activities by means of an update to the form 19 for this site.			Date: 06/06/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	It appears that the wellhead is not properly fenced. See photo documentation.		
Corrective Action:	Comply with 913.b(5)B.i. to fence to prevent access when sites are not attended.		Date: 09/04/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

