

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2024

Submitted Date:

06/04/2024

Document Number:

709100312**FIELD INSPECTION FORM**Loc ID 312218 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77069**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|-------|----------------------------|---------|
| Kym Shure | | kym.schure@state.co.us | |
| Kyle Waggoner | | kyle.waggoner@state.co.us | |
| Krystal Heibel | | krystal.heibel@state.co.us | |
| Kennedy, Herschel | | hkennedy@cogc.com | |
| Harris, Debra | | dharris@cogc.com | |
| Rogers, Bob | | brogers@cogc.com | |
| WARD, SHARON | | sward@cogc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 219649 | WELL | PR | 02/01/2023 | OW | 075-06625 | W E DICKINSON 1 | EI |

General Comment:

On May 23, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the W E DICKINSON-69N52W/6NESW location (Location ID: 312218).

The location is in close proximity to Beall Creek.

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|--------------------|---|--------|--|------------------|
| Lube Oil | WELLHEAD | | | |
| Comment: | At the time of this inspection, Staff observed a hydrocarbon release/spill at the polish rod and on nearby soil. Staff was unable to determine the approximate volume. See photo documentation. | | | |
| Corrective Action: | Immediately remove oily waste. Removal of impacted soils in excess of Table 915-1 or other remedial activities must be initiated to fully define the vertical and horizontal extent of impacts at the remediation site. Rule 912.a(5) requires that any spills or releases that do not meet the reporting requirements of Rule 912.b, Operators will document and cleanup efforts and provide documentation of the cleanup to the director upon request. Perform cleanup of this area and provide documentation of the activities by means of an update to the form 19 for this site. | | | Date: 06/06/2024 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

