



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Adequate		Date:	
Corrective Action:			Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil around the well needs to be removed. See attached photo		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 07/12/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 459148 Type: WELL API Number: 123-48736 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 26 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a></p> <p>On Tuesday, May 28, 2024, at approximately 8:40 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Location: Jagged 12N                      Operator: Chevron/PDC                      API: 05-123-48736                      County: Weld</p> <p>During the inspection, a shut in well was observed. The following possible compliance issues were identified:                      Stained Soil: Stained soil around the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." Corrective Action deadline: 7/12/2024.                      A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.                      Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	05/29/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403807767	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567683">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567683</a>
699108645	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567676">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567676</a>