

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2024

Submitted Date:

06/07/2024

Document Number:

713601091

FIELD INSPECTION FORMLoc ID 321656 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96730

Name of Operator: WILLIFORD ENERGY COMPANY

Address: 6060 AMERICAN PLAZA SUITE 760

City: TULSA State: OK Zip: 74135

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
GROWNS LARRY		lgrowns@willifordenergy.com	
Storts, Doug		pds@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207694	WELL	PR	11/01/2021	OW	017-06629	RHOADES UNIT 5-6	RI

General Comment:

This is a follow up of the previous inspection (#713600859) at the RHOADES #5-6 wellsite.
The previous inspection corrective actions have not been completed.
Operator is directed to perform all outstanding corrective actions immediately.

Location			
Lease Road:			
Type	Access		
comment:	There are areas where vehicles are driving outside of the access road boundary causing unnecessary disturbance that will need to be reclaimed. Repeated or flagrant instance(s) of failure to restrict lease access to lease roads which result in unreasonable land damage or crop losses shall be subject to a penalty under Rule 523. Previous corrective action was not completed.		
Corrective Action	Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule.	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	There is no labeling of the barrel next to the wellhead.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	There is a pile of oily rags at the south side of the location that must be properly disposed. There were aerisol cans and oil containers laying on the ground.		
Corrective Action:	Comply with Rule 606 and dispose of all containers , rags, and trash.	Date:	06/10/2024
Type	OTHER		
Comment:	There is oily fluid in the secondary containment of the barrel next to the wellhead and no wildlife protection/netting is installed.		
Corrective Action:	Comply with Rule 902. Install or repair wildlife protection equipment.	Date:	06/10/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	The spill at the wellhead was not cleaned up.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date:
Lube Oil	Pump Jack		
Comment:	There is oil still leaking from the engine. There is sand spread around the pumpjack to cover up the oil stained soils. The oil stained soils have not been cleaned up and properly disposed. Previous corrective action was not completed.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906.		Date:
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Venting:			
Yes/No			

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Fail	Material Handling And Spill Prevention	Fail	

Comment: There are areas of access road which are not stabilized or maintained. It appears there are areas where stormwater is pooling and vehicles are driving around the impacted road causing unnecessary disturbance. The access road needs to be repaired and maintained with BMP's such as road base and culverts. The roads needs to be built up to allow stormwater drainage. Previous corrective action was not completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601092	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6577861