

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403809492

Date Received:

05/31/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

MICHAEL, C

c.jackson@bp.com

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

sabre.beebe@bpx.com

DEMATTEE, SHAUNA

shauna.demattee@bpx.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000007

Inspection Date: 09/01/2023

FIR Submit Date: 09/22/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 385639

Location Name: LOBATO-N35N8W Number: 26SENW County: \_\_\_\_\_

Qtrqtr: SENW Sec: 26 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276106 Longitude: -107.716455

### FACILITY - API Number: 05-067- -00 Facility ID: 385639

Facility Name: LOBATO-N35N8W Number: 26SENW

Qtrqtr: SENW Sec: 26 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276106 Longitude: -107.716455

### CORRECTIVE ACTIONS:

1 ☒ CA# 181832

Corrective Action: Comply with rule 1004. Noxious weeds and stormwater BMP's must be removed from location.

Date: 09/01/2023

Response: CA COMPLETED

Date of Completion: 05/14/2024

Operator Comment:	Seeded bare areas and applied chemical weed treatment.		
ECMC Decision:	Approved pending re-inspection		
ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.		

2

☒ CA# 181833

Corrective Action:	Comply with rule 1004.	Date:	
Response:	CA COMPLETED	Date of Completion:	03/07/2024
Operator Comment:	Wattles and wooden stakes removed from plugged and abandoned well location.		
ECMC Decision:	Approved pending re-inspection		
ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.		

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective Action Complete, See Attached Photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson  
 Title: Permitting Specialist I

Signed: \_\_\_\_\_  
 Date: 5/31/2024 9:57:03 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403809492	FIR RESOLUTION SUBMITTED
403809524	Lobato 1-26, CA Photos

Total Attach: 2 Files