

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2024

Submitted Date:

06/04/2024

Document Number:

709100303

FIELD INSPECTION FORM

Loc ID: 312338
Inspector Name: Heibel, Krystal
On-Site Inspection:
2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:
5 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kym Shure		kym.schure@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
WARD, SHARON		sward@cogc.com	
Harris, Debra		dharris@cogc.com	
Kennedy, Herschel		hkennedy@cogc.com	
Rogers, Bob		brogers@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291455	WELL	PR	11/05/2007	OW	075-09370	SINDT 14H	EI

General Comment:

On May 23, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the SINDT-610N52W/31NESW location (Facility ID: 312338).
The location is in close proximity to Beall Creek.
Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Tumbleweeds present in fence.		
Corrective Action:	Comply with Rule 606	Date:	06/11/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (pipe and metal) located on site		
Corrective Action:	Comply with Rule 606	Date:	09/04/2024
Type	TRASH		
Comment:	Trash on site		
Corrective Action:	Comply with Rule 606	Date:	09/04/2024

Overall Good:

Spills:

Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	Stained soil located throughout site. See photo documentation.		
Corrective Action:	Removal of impacted soils in excess of Table 915-1 or other remedial activities must be initiated to fully define the vertical and horizontal extent of impacts at the remediation site. Rule 912.a(5) requires that any spills or releases that do not meet the reporting requirements of Rule 912.b, Operators will document and cleanup efforts and provide documentation of the cleanup to the director upon request. Perform cleanup of this area and provide documentation of the activities by means of an update to the form 19 for this site.		Date: 06/06/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 291455 Type: WELL API Number: 075-09370 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403813766	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573827
709100304	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573810