

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2024

Submitted Date:

06/04/2024

Document Number:

709100305

FIELD INSPECTION FORM

Loc ID 312224 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kym Shure		kym.schure@state.co.us	
Harris, Debra		dharris@cogc.com	
WARD, SHARON		sward@cogc.com	
Kyle Waggoner		kyle.waggoner@state.co.us	
Kennedy, Herschel		hkennedy@cogc.com	
Krystal Heibel		krystal.heibel@state.co.us	
Rogers, Bob		brogers@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219677	WELL	PR	04/01/2023	OW	075-06680	ARTHUR SINDT 5	EI

General Comment:

On May 23, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the ARTHUR SINDT-610N52W/31NWSW location (Facility ID: 312224).

The location is in close proximity to Beall Creek.

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

Location

Overall Good:

Emergency Contact Number:

Comment: Emergency contact number is illegible on sign.

Corrective Action: Install or repair sign to comply with Rule 605.d.

Date: 09/04/2024

Good Housekeeping:

Type WEEDS

Comment: Tumbleweeds present in fence.

Corrective Action: Comply with Rule 606

Date: 09/04/2024

Overall Good:

Spills:

Type	Area	Volume	
Lube Oil	WELLHEAD		
Comment: At the time of this inspection, Staff observed a hydrocarbon release/spill at the polish rod and on nearby soil. Staff was unable to determine the approximate volume.			
Corrective Action: Immediately remove oily waste. Removal of impacted soils in excess of Table 915-1 or other remedial activities must be initiated to fully define the vertical and horizontal extent of impacts at the remediation site. Rule 912.a(5) requires that any spills or releases that do not meet the reporting requirements of Rule 912.b. Operators will document and cleanup efforts and provide documentation of the cleanup to the director upon request. Perform cleanup of this area and provide documentation of the activities by means of an update to the form 19 for this site.			Date: <u>07/04/2024</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 219677 Type: WELL API Number: 075-06680 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403813771	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573830
709100306	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573811